

<b>PCN Number:</b>	20180605002	<b>PCN Date:</b>	June 07, 2018
<b>Title:</b>	Datasheet for LM7705		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Proposed 1<sup>st</sup> Ship Date:</b>	September 07, 2018		
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
<b>Notification Details</b>			
<b>Description of Change:</b>			
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below.			
		<b>LM7705</b>	
		<small>SNVS420D –NOVEMBER 2008–REVISED MAY 2018</small>	
<b>Changes from Revision C (September 2015) to Revision D</b>			<b>Page</b>
• Deleted 'Maximum Output Current 26 mA' from Features list .....			1
• Deleted I <sub>o</sub> _MAX spec from 3.3-V Electrical Characteristics and 5-V Electrical Characteristics tables.....			4
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
LM7705	SNVS420C	SNVS420D	
<a href="http://www.ti.com/product/LM7705">http://www.ti.com/product/LM7705</a>			
<b>Reason for Change:</b>			
To accurately reflect device characteristics.			
<b>Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):</b>			
Electrical specification performance changes as indicated above.			
<b>Changes to product identification resulting from this PCN:</b>			
None.			
<b>Product Affected:</b>			
LM7705MM/NOPB	LM7705MME/NOPB	LM7705MMX/NOPB	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>