

Date of issue : Nov. 16, 2016

Subject: Discontinue Notice of SSF-LXH475 Series

As part of an ongoing effort to offer the most appropriate solutions to user interface technology applications, Lumex is making the decision to discontinue the following part numbers from our current product offering:

SSF-LXH475 Series :

SSF-LXH475GD	SSF-LXH475AIIID	SSF-LXH475GD	SSF-LXH475GGGXD
SSF-LXH475GGIID	SSF-LXH475GGXXD	SSF-LXH475GGYID	SSF-LXH475GGYYD
SSF-LXH475GIGYD	SSF-LXH475GIIID	SSF-LXH475GYW	SSF-LXH475GYWXXSBD
SSF-LXH475GYXGYGYW	SSF-LXH475IC	SSF-LXH475ID	SSF-LXH475IGGGD
SSF-LXH475IGW	SSF-LXH475IGW2XIGW	SSF-LXH475IGW3XD	SSF-LXH475IIIAD
SSF-LXH475IIIXD	SSF-LXH475IIIYD	SSF-LXH475IXXGD	SSF-LXH475IYGID
SSF-LXH475IYGSBD	SSF-LXH475LGD	SSF-LXH475LGGGXD	SSF-LXH475LGGIID
SSF-LXH475LGIGGD	SSF-LXH475LGIYXD	SSF-LXH475LGXYGD	SSF-LXH475LGYGYD
SSF-LXH475LID	SSF-LXH475LIIIXD	SSF-LXH475LSBGYID	SSF-LXH475LYD
SSF-LXH475SBGYID	SSF-LXH475SGC	SSF-LXH475SI2SOSUG	SSF-LXH475SID
SSF-LXH475SRC	SSF-LXH475SRD	SSF-LXH475SUGD	SSF-LXH475SYC
SSF-LXH475USBD	SSF-LXH4755XGYGYGYW	SSF-LXH475YD	SSF-LXH475YGW
SSF-LXH475GYW3I1D	SSF-LXH475YGWXYGWI	SSF-LXH475YYGGD	SSF-LXH475AYYYD5V
SSF-LXH475GAYID	SSF-LXH475GIYXD	SSF-LXH475GYGYD	SSF-LXH475GYYID
SSF-LXH475IAYGD	SSF-LXH475IGIGD	SSF-LXH475YGW3I1D	

Discontinue above part immediately.

As there is no direct replacement for this product, please contact Lumex Technical Specialists for customer support to transition any customers you might have to a new product.

If you have any questions, feel free to contact your Lumex representative for more information.

(END of the EOL)

Best Regards,

Lumex Product Management Team