## NALOG Product Discontinuance Notice - PDN 12\_0038 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

## PDN Title:

Publication Date:	09-Mar-2012		
Last Time Buy Date:	09-Mar-2013		

Last Time Ship Date: 09-Mar-2014

## Reason For Discontinuance

Discontinuing this product due to decreased customer demand.

## Comments

Recommended replacement parts are not a direct fit. A number of products to consider are listed in the Material Report Summary.

Supporting Documents None

	For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive					
Americas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan: Rest of Asia:	PDN_Japan@analog.com PDN_ROA@analog.com	

PDN 12_0038 Discontinued Parts Material List				
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADuM1420BRWZ	ADUM1420	See Comments	No	Consider other isolated gatedrivers: ADuM3220ARZ, ADuM3220BRZ, ADuM3221ARZ, ADuM3221BRZ, ADuM5230ARWZ, ADuM6132ARWZ, ADuM7234BRZ, ADuM3223ARZ, ADuM3223BRZ, ADuM3223CRZ
ADuM1420BRWZ-RL	ADUM1420	See Comments	No	Consider other isolated gatedrivers: ADuM3220ARZ-RL7, ADuM3220BRZ-RL7, ADuM3221ARZ-RL7, ADuM3221BRZ-RL7, ADuM5230ARWZ-RL, ADuM6132ARWZ-RL, ADuM7234BRZ-RL7, ,ADuM3223ARZ-RL7, ADuM3223BRZ-RL7, ADuM3223CRZ-RL7

Appendix A - PDN 12_0038 Revision History						
Rev	Publish Date	Rev Description				
Rev	09-Mar-2012	Initial Release				
			And a Definition Devictory Information	Deside 407 Les el De O	B B HINK	

Analog Devices, Inc. Proprietary Information

Docld:467 Layout Rev.2 Parent Docld:None