

## 



## **Affected Parts**

Models
2VAQ-4A
2VAQ-4B
2VAQ-4G
2VAQ-4R
2VAQ-4W
2VAQ-4Y
SEPARATOR FOR VAQ-37SH
VAQ-15A-L
VAQ-15B-L
VAQ-15G-L
VAQ-15R-L
VAQ-15W-L
VAQ-15Y-L
VAQ-37B
VAQ-37R
VAQ-37R V-10-1E5SN
VAQ-37R V-15-1B5
VAQ-37RSH V-10-1E5SP
VAQ-37W
VAQ-37WSH V-10-1E5SP
VAQ-4A-K
VAQ-4A-L
VAQ-4B-K
VAQ-4B-K V-15-1B6

Models
VAQ-4B-L
VAQ-4G-K
VAQ-4G-L
VAQ-4R-K
VAQ-4R-L
VAQ-4W-K
VAQ-4W-L
VAQ-4Y-K
VAQ-4Y-L
VAQ-K
VAQR-4A
VAQR-4B
VAQR-4G
VAQR-4R
VAQR-4W
VAQ-4A-K
VAQ-4A-L
VAQ-4B-K
VAQ-4B-K V-15-1B6
VAQ-4B-L
VAQ-4G-K
VAQ-4G-L
VAQ-4R-K
VAQ-4R-L

Models
VAQ-4W-K
VAQ-4W-L
VAQ-4Y-K
VAQ-4Y-L
VAQ-K

Models
--------

VAQR-4A VAQR-4B VAQR-4G VAQR-4R VAQR-4W

Specifications in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.