

Product Change Notification (PCN)

PCN Number	502888	Date Issued	August 01, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	Passed FAI		
Internal Molex Qualification Date	August 01, 2017		
Sample Availability Date (Changed Part)	August 01, 2017		
Planned Implementation Date	August 17, 2017		
Method of Identifying Change	Product made after pla change	nned implementation	on date can contain the

Before Change

 Housings Plug & Cap 2.13 Dia ,42021 & 42022 serieswithout ribs at the bottom of the hub as shown below



molex

After Change

Overview

- To provide the supporting ribs to hub in the MLX series of Plug & Cap housings as shown in below pictures. These additional supporting ribs are being added to provide extra strength to the hub so that it do not get pulled out from its position during molding process. This correction is planned for 12 Molds.
- Product Impact -This change will have no impact or Fit/Function of the product
- Part Number Impact –refer attached
 Pet number
 In-5028
- PPAP and samples available upon request



molex

molex

Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502888**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

Molex Part

Part Numbers Affected:		
Molex Part #		
50-84-1010		
50-84-1020		
50-84-1030		
50-84-1040		
50-84-1045		
50-84-1060		
50-84-1090		
50-84-1120		
50-84-1125		
50-84-1150		
50-84-2010		
50-84-2020		
50-84-2030		
50-84-2032		
50-84-2040		
50-84-2042		
50-84-2060		
50-84-2062		
50-84-2090		
50-84-2092		
50-84-2120		
50-84-2122		