1 Products affected

Product hierarchy no. *				Part no.	Type / Description	Customer part no.
SBU	PG	PGU	Туре			
01	001	122	000000122	0001.2704.22 - 0001.2716.22	Fuses / SMD-SPT	
01	001	120	000000120	0034.5604.22 - 0034.5630.22	Fuses / SMD-FST	
01	001	121	000000121	0034.5705.22 - 0034.5719.22	Fuses / SMD-FTT	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change

Change of packaging

- Packaging of 2000 pieces is no longer available

- Coil for the supply of 1'000 units is adjusted

3 Detailed description of change

The coil outside diameter changed from 380 mm to 330 mm. The color is new blue instead of black.

4 Reason of change

Optimization of the coil on the 1000 units.

5 Released date

This change is effective from production date 2010-08-17.

6 Impact of change and recommended action

New outside diameter of the coil
The coil diameter has changed from 380mm to 330mm.
None
None

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
drawing	0504.0257	

09.09.2010 SMA 02.12.2010 HRÜ 21682 1 vor		0118.2047					
SMA 02 12 2010 HRU 21682 1 1 Vor	Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
15:08:28	09.09.2010 15:08:28	SMA	02.12.2010	HRÜ	21682	_	1 von 1

Print date: 02/12/2010 13:42:00